


ULTIMETER 2100
Keyboard Display



AC Adapter



Junction Box Cable



Wind Sensor



Junction Box

- OR -

Duplex Cable
(Optional)



Indoor Humidity Sensor
(Optional)



PC Data Logger
(Optional)

OR



The Weather Picture
(Optional)



Rain Gauge (Optional)



Outdoor Humidity/Temperature Sensor (Optional)



Temperature Sensor

* Connection of both
The Weather Picture
AND a PC Data Logger
to the i/O port requires a
Duplex Cable.